





Photo 5: Boring 4BE(10') 4.5-5' at southeastern corner of the pressure wash room inside the manufacturing/office building.



Photo 6: Boring SB-34 located inside the manufacturing/office building.



Photo 3: Soil borings 2CW(10') and 2CW(20') located west of stormwater collection sump and pump along southern border of the Site.



Photo 4: Soil boring SB-40 located in unpaved area immediately west of paved parking area.














Photo 7: Nested well (NW-1) located along northern border of Site before installation of traffic box.



Photo 8: Nested well (NW-3) located along southern border of the Site after installation of traffic box.











Photo 9: TEG's mobile laboratory shown on the Site in December 2005.



Photo 10: BC² Environmental drill rig and support truck during installation of nested well NW-2.



Photo 11: BC² Environmental crew during installation of nested well NW-2.



Photo 12: BC² Environmental crew during installation of nested well NW-3.



Photo 13: BC² Environmental crew steam cleaning augers used for drilling nested wells.



Photo 14: Sampling equipment used during collection of groundwater samples from nested wells.







